Property Appraisal Checklist



Property address: Full name of owner(s):	60 Oceanic Drive Sea View Cassandra Bernice Mather and Anthony Frank Huddle							
Date of appraisal:	11 /04 /19	By (agent): Rick Hamilton						
Contact details:	(H) 97296387 (M) 0412744982	(W) (E) cmather@hopkinshop.com						
Name of tenant: Contact details:	N/A (H) (M)	(W) (E)						
Rental term & rental price:		_/						

Land area		728	sqr	n					Ζοι	ning	J	R20)					
Location/nearby amenities				Near	Near ocean													
Statutory p	tutory particulars Location			Garriden Plan			an diag	ag. 176 Lot 102				2	Vol.	7	Folio	2		
Rates	City council (Blue Sky City)			ty)		\$2200 Water Authority					у		\$360					
Services	Elec	ctricity	\checkmark	Gas	\checkmark	Water	Bo	re	Ma	ains	\mathbf{v}^{t}	Rain	water		Sewer	4	Septic	
Constructio	Iction Fibro and tin								Bu	ilde	r	Sair	nsbur	ys				
Style	Bun	galow							Ag	е	50							
Area (sqm)		Living	13	0sqm		Veran	dahs	20s	qm		Gar	age	16m2		Car	oort		

Feature	Description
Front garden	Several established trees, well kept lawn.
Front façade	Attractive, but needs painting.
Garage	One car with garage door (self standing)
Car port	None
Verandah	Outside front door, quite spacious, tiled
Entry hall	Narrow, dark
Lounge	Large with wood picture rail on wall, old curtains, reasonable carpet, ceiling
	rose
Formal dining	Large but dark, ornate ceiling rose same carpet as lounge
Hallways	Features ornate jarrah frames at each end
Casual meals	Located in kitchen, cramped
Kitchen	Original and small, gas cooking and old linoleum floors
Family room	N/A
Games room	N/A
Home theatre	N/A
Bedroom 1	Large with stained glass window. Ceiling fan and ceiling rose. No curtains.
Ensuite	N/A
Bedroom 2	Reasonable size but carpets need replacing. Very old curtains.
Bedroom 3	N/A

Bedroom 4	N/A										
Bedroom 5	N/A										
Bedroom 6	N/A										
Study	N/A										
Sleep out	Flat asbestos roof, needs new floor coverings, feels damp.										
Main bathroom	Terrazzo floors, large bath and shower, 50's style.										
Bathroom 3	N/A										
Toilets (x 1)	Contained in main bathroom										
Laundry	Outdoor laundry – very rundown, old trough etc.										
Insulation	According to ver	ndor N	lone	-			-				
Hot water system	Gas						Elect	ric	storag	ge (old)	
Shed	2 large tin	sheds	s (one	in disrep	air, lea	kin	g ro	of etc)			
Back garden	Neat with f						0	,			
Swimming pool	N/A										
Window treatments	Very old Holland blinds, limited coverage										
Built in furniture	N/A										
Pergola	N/A										
Reticulation	Mains Bore Auto Manual										
Extras	BBQ			Security system			Intercom			Clothes line	
	TV antenna			Ducted vacuum			Retaining			Fencing	Timber picket
Climate control	Split system	system			Ducted evaporative			Ducted reverse cycle		Gas heater	
	Fireplace					Ot					
Presentation	Low			N	ledium				High		
Views	180 degree developed.	ocean	views	s from gr	ound le	evel,	Un	limite	d views	if 2 nd s	torey
Road	Quiet			N	ledium				Busy		
Development potential	Large block	, suit	t duple	ex or rend	vate/re	dev	elopi	ment -	- 2 nd sto	orey for	views.
Property restrictions	None										
Proposals which may affect property	None										
Price current owner paid	\$120 000 J	lune 1	1985								

Summary	Given that the block has suburb ocean views but the house is 50 years old, is fibro and tin in construction and has not been well maintained, it is very likely the next owner will redevelop the site. There are already several redeveloped sites in the street and surrounding areas. The value of the property is likely to be in its block value but some consideration needs to be given to the house as extensive renovations could be done.

Recommendations	The exterior of the house could be painted to improve its street appearance and the laundry could be cleaned up.

Comments	Needs TLC. Good development potential, growth area. Could have cottage value/charm.